

Jeff Shelquist

From: "Dustin strafe" <dustin.strafe@gmail.com>
Date: Saturday, August 28, 2010 5:35 PM
To: "Jeff Shelquist" <jeff_shelquist@hotmail.com>
Cc: "Lawrence" <lawrence@strafeautomotive.com>
Subject: Re: Pics of the defective StrafeSpeed bumper

As we have told all others in the past if you want to go ahead and post the pics on the forum then you can. Do realize once you do so it will be more difficult to resolve with us because you are using the muscle of the forum to get your way. Those pics are terrible by the way, please send me better pictures of figment and of the problem areas. Extreme close ups don't really show me anything. More than happy to take a look at everything and i will talk to my partner to see what we can do for you. Thanks.

Dustin

Owner Strafe Automotive

www.strafeautomotive.com

On Aug 28, 2010 2:21 PM, "Jeff Shelquist" <jeff_shelquist@hotmail.com> wrote:

Dustin,

The pictures were taken with my cell phone. You can see the delamination bubble, its about the size of a dime. The last picture shows the back of the delamination spot. The other photos show the puddle of resin without any fibers.

If you can show me that new, top-quality fiberglass aftermarket bumpers routinely contain delamination bubbles and it is generally accepted that such defects will be present when you purchase such a product then fine. But the bumper you sent me was poor quality and contained manufacturing defects.

Let's post the issue on G35Driver and let people vote. Normal FG bumper vs. CRAP. I will go take some pictures with a quality camera and post the pics and let the people decide.

Jeff