

Work Order ID
Customer Number
Name
Vehicle (VIN)
Technician
Mileage
Time Printed




55771
5/8/14 4:20 PM


Infiniti 07-08 G35 Sedan 4X2 225/50R18

After w Trunk Backseat Full & Fuel tank Full

Current Measurements



maxed out on adjustment
may need new spring or strut to stay within spec



Still has 0.1° or so adjustment left.

Why left side faster than right? Gas tank? strut/spring wearing

- The steering wheel is currently level.