

**AMClassification:**
**Reference:**
**Date:**

BT06-028

ITB06-025

November 17, 2006

## '05-'06 G35; GLOVE BOX LID FIT AT TOP EDGE

**APPLIED VEHICLE(S):** 2005-2006 G35 (C/V35)

### IF YOU CONFIRM

The gap between the top edge of the glove box and the instrument panel is more than normal

And/or

The glove box light stays on when the door is closed.

### ACTION

Use the Service Procedure to adjust the glove box latch to reduce the clearance/close the door further.

### PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
Washers (10 count received per part number order)	08915-4361A	1 (per car)
3M Weatherstrip Adhesive	Local source	(*)

\* This is considered a shop supply.

### CLAIMS INFORMATION

Submit a Primary Operation (PO) line claim using the following claims coding:

DESCRIPTION	OP CODE	SYM	DIA	FRT
Install Glove Box Latch Washers	VX79AA	FA	45	0.2 hrs

**IMPORTANT:** The purpose of "ACTIONS" (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire Service Procedure (starting on page 2) as it contains information that is essential to successfully completing the repair.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.

## SERVICE PROCEDURE

1. Remove the two glove box latch screws.



2. Using thin double-sided tape or a small amount of glue (3M Weatherstrip adhesive or equivalent) attach one washer per side as spacers to the back side of the latch.



3. Install the latch and check the door fit.
  - If the fit is now OK, operation is complete.
  - If the fit is still a bit loose, repeat steps 1 – 3 above with the remaining two washers from the kit.

**NOTE:** Do not use more than two washers per side (four washers total).