

10INZ06	LABOR TYPE	LABOR HRS	LABOR \$	PARTS \$	TOTAL
	C	10.00	\$ 1628.00	\$ 1014.04	\$ 2642.04

CHECK ENGINE LIGHT ON CUSTOMER STATES VEHICLE FELT LIKE IT WAS STALLING

P0021 INTAKE VALVE TIMING CONTROL-B2, P0024 EXHAUST VALVE TIMING CONTROL-B2 * REMOVE TIMING COVER & INSPECT OIL GALLEY GASKETS & TIMING CHAIN COMPONENTS

PART #	PART DESCRIPTION	QTY	UNIT \$	TOTAL
13533JK21A	GALLEY GASKET	1	\$ 41.76	\$ 41.76
13533JK21B	GALLEY GASKET	1	\$ 9.24	\$ 9.24
13040JK30B	B2 VTC COVER IF NEEDED	1	\$ 795.75	\$ 795.75
23797EY01A	VTC COVER GASKET B1	1	\$ 78.24	\$ 78.24
237979N00B	VTC COVER GASKET B2	1	\$ 9.03	\$ 9.03
15066ZL80D & 15066ZL80C	TIMING COVER O-RINGS	2	\$ 7.84	\$ 15.68
1351031U10	FRONT CRANKSHAFT SEAL	1	\$ 15.51	\$ 15.51
LOCALSEALANT	RTV LIQUID GASKET	1	\$ 19.95	\$ 19.95
LOCALENOIL	5W30 OIL	6	\$ 3.25	\$ 19.50
1520865F0E	OIL FILTER	1	\$ 9.38	\$ 9.38

90INZ05	LABOR TYPE	LABOR HRS	LABOR \$	PARTS \$	TOTAL
	C	0.00	\$ 0.00	\$ 0.00	\$ 0.00

COMPLIMENTARY WASH & VACUUM

03INZINSP	LABOR TYPE	LABOR HRS	LABOR \$	PARTS \$	TOTAL
	C	0.00	\$ 0.00	\$ 0.00	\$ 0.00

PERFORM MULTI-POINT INSPECTION

SUB-TOTAL ESTIMATE WHEN APPROVED	LABOR HRS	LABOR \$	PARTS \$	TOTAL
	10.00	\$ 1628.00	\$ 1014.04	\$ 2642.04