

Classification:

Reference:

 COPYRIGHT © NISSAN NORTH AMERICA, INC.
 Date:

BT09-051

ITB09-060

October 30, 2009

2007-2009 G SEDAN; DOOR OUTSIDE MOLDING(S) COMING APART

APPLIED VEHICLE: 2007-2009 G Sedan (V36)

IF YOU CONFIRM

The rubber portion of a door outside molding(s) on an Applied Vehicle is coming apart and/or transferring black rubber material when touched.



ACTION

Replace all four (4) door outside moldings with the ones listed in the Parts Information section.

- Refer to the "EXT" section in the applicable Electronic Service Manual (ESM) for removal/installation instructions.

PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
Moulding Assy - Front Door Outside, LH	80821-JK00D	1
Moulding - Rear Door Outside, LH	82821-JK00D	1
Moulding Assy - Front Door Outside, RH	80820-JK00D	1
Moulding - Rear Door Outside, RH	82820-JK00D	1

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPL ONE DOOR OUTSIDE MOLDING (FRONT)	(1)	UH16AA (2)	ZA	13	(3)
RPL ONE DOOR OUTSIDE MOLDING (REAR)	(1)	UK16AA (2)	ZA	13	(3)

- (1) Reference the Parts Information Table and use the applicable Molding P/N as the PFP.
- (2) When submitting claims, submit the front doors on one repair line and the rear doors on a separate repair line to be used 2 times.
- (3) Reference the current Infiniti Warranty Flat Rate Manual and use the indicated FRT.

