

Work Order ID  
Customer Num  
Name  
Vehicle (VIN)  
Technician  
Mileage  
Time Printed




55771  
5/8/14 3:55 PM


Before w/ Trunk / Backseat Full + Fuel Tank Full

Infiniti 07-08 G35 Sedan 4X2 225/50R18

Current Measurements



Weak Spring or Strut?



The steering wheel is currently level.